CORNER RECORD

Agency Index

BK21 Pg 97

| Document | Number | 201900 | 33 |
|----------|--------|--------|----|
| | | | |

| City of | Rocklin | County of _ | Place | r, California | 3 |
|---|----------------------------------|--|---|--|---------------------|
| Brief Legal Description | The CL of V | Vildcat Blvd. N. of \ | West Standford Rand | ch Road per T Maps 49 | _ |
| CORNER TYPE | | | COORDINATES (Optional) | | 10 12 |
| | Government C Meander Rancho | orner Control Property Other | Elevation Units Metric Horizontal Datum | E. U.S. Survey Foot | _ |
| SEC 18, T.11N., R.7.E. | Date of Survey | June 6, 2019 | Vertical Datum Complies with Public | | |
| PLS Act Ref.: | 3765(d) | × 8771 | 8773 | Other: | _ |
| Comen | eft as found Found and tagged | Established Reestablished | Rebuilt Referenced | Pre-Construction Post-Construction | _ K |
| Narrative of corner identified See sheet #2 for descrip Set reference points t | tion(s): | | | as shown on sheet 2 | 2 |
| This Corner Record was prep the Professional Land Survey Signed | yors' Act on <u>July</u> | my direction in conformal 15, 2019 _P.L.S. or R.C.E. No. | nce with | Exp. 9-30-07 No. 6947 OF CALIFORN | CORNER RECORDS PAGE |
| This Corner Record was record and examined and filed Signed Title Defice County Surveyor's Comments | July 2: Bulloner Server | 75,2019 3,2019 • P.L.S. or R.C.E. No. | <i>B</i> 373 | No. 8373 No. | 97 |

